

# COLUMBIA PRODUCTS SANI-LAV<sup>®</sup>


## Faucets



Model 2003L



Model 2002



Model 1001



Model 2005



Model 2004




Model 2007




Model 2006


■ Model 1001




■ Model 2002




■ Model 2003L




■ Model 2004




■ Model 2005



■ Model 2006




■ Model 2007



**Replacement Parts**

Part No.	Description	Quantity	Universal Part
<b>A</b>	2004-1 Faucet Body Assembly	1	YES
<b>B</b>	1062-C Faucet Valve Repair Kit - Cold	1	NO
<b>C</b>	1062-H Faucet Valve Repair Kit - Hot	1	NO
<b>D</b>	2004-2 Female Wall Flange Assembly	2	YES
<b>E</b>	2004-3A Bonnet Nut - Cold	1	NO
<b>F</b>	2004-4A Bonnet Nut - Hot	1	NO
<b>G</b>	2010-1 Handle 6" inch - Cold	1	NO
<b>H</b>	2010-2 Handle 6" inch - Hot	1	NO
<b>I</b>	2011-1 Handle 4" inch - Cold	1	NO
<b>J</b>	2011-2 Handle 4" inch - Hot	1	NO
<b>K</b>	2012-1 Handle 2.5" inch - Cold	1	NO
<b>L</b>	2012-2 Handle 2.5" inch - Hot	1	NO
<b>M</b>	2004-5 10-24 Oval Csk Screw x .5"	2	YES
<b>N</b>	2003-1 Swivel spout Assembly	1	YES
<b>O</b>	2001-1 12" swivel spout Assembly	1	YES
<b>P</b>	2002-1 6" swivel spout Assembly	1	YES
<b>Q</b>	1002 55/64 - 27 Female aerator	1	YES



Part No.	Description	Quantity	Universal Part
<b>B</b>	<b>1062-C Faucet Valve Repair Kit - Cold</b>		<b>NO</b>
<b>1</b>	Seat	1	YES
<b>2</b>	Seat Washer Screw	1	YES
<b>3</b>	Seat Washer	1	YES
<b>4</b>	O-ring	1	YES
<b>5</b>	Valve Stem	1	NO
<b>6</b>	Bonnet Nut Washer	1	YES
<b>C</b>	<b>1062-H Faucet Valve Repair Kit - Hot</b>		<b>NO</b>
<b>1</b>	Seat	1	YES
<b>2</b>	Seat Washer Screw	1	YES
<b>3</b>	Seat Washer	1	YES
<b>4</b>	O-ring	1	YES
<b>5</b>	Valve Stem	1	NO
<b>6</b>	Bonnet Nut Washer	1	YES